

7. Properties

7.1 Dimensions [mm]: (at room temperature)

Pos.	W	H	S	Y	X	R	Cumulative step error about 80 steps	Z
265-605/2.5	2,65 +0,10/-0,15	2,05 ±0,10	0,30 ±0,01	0,56 +0,02	0,89 +0,10	2,50 ±0,02	Max. ±0,10	1,00 ±0,03
265-635	2,65 +0,05/-0,15	2,05 ±0,10	0,30 ±0,01	0,59 +0,02	0,89 +0,10	2,54 ±0,02	Max. ±0,10	1,00 ±0,03
220-390/2.5	2,20 ±0,10	1,70 ±0,10	0,30 ±0,01	0,35 +0,02	0,75 +0,10	2,50 ±0,02	Max. ±0,10	0,85 -0,06

7.2 The bandolier must be free of twist, shall be consistent for the whole length.

7.3 The maximum sabre curative at measuring length 500mm is 4mm in both direction

7.4 Maximum 2 breaks on coil allowed, coil and label to be marked